•	18/8/24	
_	7	1
חני ופעימים	10	
S		

• ,		,		cold	1
SEPA	POTENTIAL HAZARDOUS W SITE INSPECTION RE		ه حسنسیمی	j ed \$1	NUMBER (10 to seeign He) 03115
tion on this form to develop a ? File. Be sure to include all as	complete Sections I and III through : l'entative Disposition (Section II). propriate Supplemental Reports in t System; Hezardous Vaste Enforcem	File this form the file. Subm	in its entirety in it is copy of the	n the regional Ha forma to: U.S. E	zardous Weste Log nvironmental Pro-
A. SITE HAME	I. SITE IDEN		other identifies)		
Force, Inc.			nda le	·	
C. CITY HOUSTON TXD 07 G. SITE OPERATOR INFORMATIO	4165986	TX	77023	Harris	ME
(Same as above)		·		(713) 92	
R. HEATTY NAMES INFREDITIE	N (II diliorent from operator of else)	···	-		
I. HAME	a (it distarant tedm obstator of bids)			2. TELEPHON	E NUMBER
(Same as above)	. The state of the			A. TTATE	\$. 210 CODE
Waste oil recovery	tacility				
TYPE OF OWNERSHIP	TATE 3. COUNTY 4	, MURICIPAL	[√] 5. ₽RIV	ATF	
Call to Paraction Call to S		, morner ne			
A. ESTIMATE DATE OF TENTAT	U. TENTATIVE DISPOSITION VE B. APPARENT SERIOUSNESS		s section last)		
DISPOSITION (mo, day, & yn)	1 <u></u>	F WEDIAM	1. LOW	T 4. HONI	
C. PREPARER INFORMATION 1. NAME		2. TELEPHON	E NUMBER		for. & rn)
Thomas J. Stang		(713) 94.		2/21/84	
A. PRINCIPAL INSPECTOR INFO	III. INSPECTION	INFORMATIO	. ж		
Thomas J. Stang		s. tites Project i	Manager		
Engineering-Science	. Inc. 9920 Guli Fre	-Gway		1713) 943	ENC.(eres code & no.)
I NAME	2. 0#64%			3.200	Partie i.s.
Thomas J. Stang	Engineering-Scien			(713) 943	
Philip S. Liang	Engineering-Scien	nce, Inc.	-	(713) 943	-50 55
Susan Ripley	TOWN Region Zo			(713) 479	-5981
C. SITE REPRESENTATIVES INT	ENVIEWED (composes ellicials, morker z. TITLE 1 7.ELEPHONE NO.	e, residents)		ADORESS	
Don Forse	President (713) 928-2787 (2)	Hous	Lawndaie: ton, TX 7		
James R. Greenlee	Env. Compliance Offi (713) 984-2737	icer 7026 Houst	Lawndale Lon. TX Z	7023	
Homer Shealy	Treasurer (712) 928-2737		Lawndale Ico. IX 7	7023 SULVE	History City
		:		FB	0.1 (89%)
		_		av Of	RGANIZES:
		1 OF 10			we On Reverse

PAGE 1 OF 10

Continued From Front III. INSPECTION INFORMATION (continued) D. GENERATOR INFORMATION (SOURCES OF PROCES) 2. TELEPHONE NO. 2. 400RESS 4. WASTE TYPE CENERATED (Waste oil received from various industrial clients) E. TRANSPORTER/HAULER INFORMATION I. NAME I. TELEPHONE NO. --4. MASTE TYPE TRANSPORTED 7026 Lawndale Waste oil (713) 928-2737 Force, Inc. Houston, TX 77023 waste oil emulsion P. IF WASTE IS PROCESSED ON SITE AND ALSO SHIPPED TO OTHER SITES, IDENTIFY OFF-SITE FACILITIES USED FOR DISPOSAL. 1. NAME 2. TELEPHONE NO. J. ADDRESS Reclaims waste oil and waste oil emulsions Force, Inc. and sells the oil to various customers M. TIME OF INSPECTION I. ACCESS GAINED BY (credentials must be shown in ell cases) (mo., der. & ro.) 2-16-51 8.30 am-11:30 dm (2) 1. PERMISSION 2 WARRANT J. WEATHER (Moseribo) 65° F Sunny No wind IV. SAMPLING INFORMATION A. Kark 'X' for the types of samples taken and indicate where they have been sent s.g., regional inb, other EPA tab, contractor, etc. and estimate when the results will be available. 2. BAMPLE 1. SAMPLE TYPE TAKEN (mark!3") S. SAMPLE SENT TO: RESULTS A. ERGUNDWATER (None taken) L JURFACE WATER 4. WASTE & RUNOFF & SPILL g. 20:L B. FIELD MEASUREMENTS TAKEN folder radioactivity, explanivity, PE, etc.) 2. LOCATION OF MEASUREMENTS 3. A C SUL TS: (None taken)

PAGE 2 OF 10

Continue On Page 3

EFA Fee 12070-3 (10-79)

Continued From Page 2	<u> </u>		
	IV. SAMPLING INFO	RMATION (continued)	
C. PHOTOS			
1. TYPE OF PROTOS		IN CUSTODY OF	
A. GROUND D. AE	Engil	neering-Science, Inc.	·
D. SITE MAPPED!	See Site I	Diagram, Figure 1	
TYES. SPECIFY LOCATION	and 7.5 M	inute Quad Sheet	
E. COORDINATES			
t. LATITUDE (degi-mini-190.)		2. LONGITUDE (degi-mini-sec.)	
2	29 ⁰ 42' 57" N	95 ⁰ 17' 53" W	
	V. SITE INF		
A. SITE STATUS			
1. ACTIVE (Those inductrial of minimizations after which are being us for waste treatment, storage, or dien on a continuing basis, even if introquently.)	sad sifes which no longer receive isposel wastes.)	3. OTHER (specify): (Those area: ther include such includes where no regular or communing use has occurred.)	
B. IS GENERATOR ON SITE			
1. NO 2. YES(ap	pacify generator's foundigit SIC Code)	
C. AREA OF SITE (In acres)	D. ARE THERE BUILDINGS	CN THE SITE!	
		mocity) Office, mainten	ance area.
1.3		unload area	
	VI. CHARACTERIZATI		
Indicate the major site activity(s		ctivity by marking 'X' in the approp	priate boxes.
X1.	1x1	lx:	X
A. TRANSPORTER	X B. STORER	C. TREATER	O. DISPOSER
1. RAIL	1.PILE	1. FILTRATION	I. LANDFILL
2.5HIP	2. SURPACE IMPOUNDMENT	3. INCINERATION	2. LANDFARM
3. BARGE	X 3. DRUMS	3. VOLUME REDUCTION	3. QPEN DUMP
Y 4. TRUCK	Y 4. TANK, ABOVE GROUND	. RECYCLING/RECOVERY	4.SURFACE IMPOUNDMENT
9. PIPELING	Y P. TANK, BELOW SROUND	S. CHEM./PHYS./TREATMENT	S.MICHIGHT DUMPING
S. OTHER (specify):	4. OTHER (apacily):	6. BIOLOGICAL TREATMENT	S.INCINERATION .
		X 7. HASTE OIL PEPRICESSING	T.UNDERGROUND INJECTION
		S. SOLVENT RECOVERY	8. O THER (apacity):
•	1	S. OTHER(opecity):	
	1	Γ .	
			<i>,</i>
·	}	1	
	<u></u>		<u> </u>
	f the site falls within any of the emeg have filled out and attached to this fo	eries listed below, Supplemental Repor ft.	is must be completed. Indicate
I :. STORAL	2. INCINERATION 3. LANGE	LL 4 SURFACE	& DEEP WELL
A 6. CHEN/BIO/	7. LANDFARM B. OPEN D	UMP 🔼 9. TRANSPORTER 🛣	TO: RECYCLOR/RECLAIMER
	VII. WASTE RELAT	FED INFORMATION	
A. WASTE TYPE			
X 1. LIQUID	2. SOLID 🛒 💢 9. SLUDGE	4. GAS	
B. WASTE CHARACTERISTICS	<u> </u>		
			ن ر احد ز
1 CORPOSIVE		CTIVE 4. HIGHLY VOLATILE	و ا
si doxic	S. REACTIVE S T. INERT	B. FLAWMABLE	ें कर्म ^{के} ब्रोग
- tu	laste oil and oil water	omule ione	i
C. WASTE CATEGORIES	·		
1. Are records of wastes available:	of Specify (tems such as manifests, in	wentedes, etc. below.	
Man	ifests and Registratio	n ÷33969	

EPA Ferm T2070-3 (10-79)

PAGE 3 OF 10

Continue On Reverse

-	Prom From	1.								_		·		· 	
-	Fatinate the age:	an Consular man of			RELATED					_					
-	. Estimate the amou	b. OIL	7		LVENTS	TEE		ENICA	_		4. SOL 105		•	ieni. I. G*=I	
4	40UNT	AMOUNT				+	-0UNT			-	-CU-47		٠,	-00 4 ·	
	None	600		None	3 .		None		l		None		l	lone	
U×	IIT OF MEASURS	ton/year	1	AIT 0 F	MENTURE	1	NIT 0#	₩E ASU	**	Ų,	OF MEAS	u4 E		? OF WE	4 3 U T E
· *	FAINT.	Y THE TES	F	11 801	LOGENATES	· F	11. AC	01			111 F L V & SH		-	· > 100	4708¥ 408¥7.
	(4) METALS	21 OTHER(erec		12,70	".MALGGM"	3.	21 210	K L:NG			121:4998376	1	i	/2· H01911	AL
	(3) POTW	Oily sludg from DAF	+	1,07	nen (operly,	7	131 CAL	117161		_	137 MILLING	MINE	İ	(3 · 7 A B 10 ·	CTIVE
7	(4) ALUMINUM SEUDGE	unit and settling p	it			1	41 0 2 8	T1C101			IA. PERROUS		 	141	PAL
	to O THER (specify);						9.0.0	3/1NK	.		'S' NON-PER	AOUS ASTES	<u> -</u>	SICTHE)	(aBecaty)
	odata sa t	,					101 C Y	NIDE		_	· OTHERIO	P=CUIT)	- -		
						-	(7) 0-1	CHOLS	\dashv						
						-	181 HAL	.06EN					1.		
						-	PC					.			
						-	1101 NE	7468						٠	
							11107	HERISH	o Cilvi		٠				
		. •				Ì		•	1						
D.	LIST SUBSTANCES C	F GREATEST CON	CERN	WHICH	ARE ON THE	SIT	E /Blace	III de si	ending	97	der at hazerd:		<u></u>		
<u> </u>				. FORM	1	. 70	RICITY			_		1			
	1. SUBSTA	HCE .	1.50°		2 - A - 4.	7 8.		d.	4. C		NUVBER	5.4	MO	PUNT .	6. UNIT
1	,1,1 Trichlor	roethane		X		X			71-	5.	5-6	None at p		n site sent	
_	(Past unauthorize	d receipt of	a s	h i pine	nt. Ma	er	ial	is no	lon	g	er on si				
						Ī				_					
	· · · · · · · · · · · · · · · · · · ·														
										_					
										_					
	and the same of th					-									
	· .														
					D. HAZARI					_					
	ELO EVALUATION zard in the space pr		IFTIC	N: PL	ice sa 'I' ii	n the	bex to	ındice			e listed héz	ard exis	18.	Describe	the
Ī	AŽHUMAN HEALT	H HAZARDS			بو				4						
				÷ _e					ټ.						•
					. 3						2 3			•	
	. • }							:							
								-							

PAGE 4 OF 10

Continue On Page 5

Continued From: Page 4	
E. NON-WORKER INJURY/EXPOSURE	VIII. HAZARD DESCRIPTION (continued)
E. RON-WORKEN INJUNT/EXPOSURE	
	•
	•
. •	
C. WORKER INJURY/EXPOSURE	
·	
ar .	
	an and the second secon
D. CONTAMINATION OF WATER SUPPLY	
D. GORIANIALIUM D. MATER SUPPLY	
•	
	·
T. CONTAMINATION OF FOOD CHAIN	
2. CONTABINATION OF POOD CHAIN	
•	·
	·
F. CONTAMINATION OF GROUND WATER	
	name or sure
.4	
G. Contamination of Surface water	
- 特 - 表記	
•	
<u>;</u>	
•	
	PAGE 5 OF 10 Continue On Keverse

H. DAMAGE TO FLORA/FAUNA	VIII. HAZARD DESCRIPTION (continued)	
H. DAMAGE TO PLOTA/FAUNA		
	•	
		· · · · · · · · · · · · · · · · · · ·
I. FISH KILL		•
1.4 · .	e en e	(19 an
,		
•		
J. CONTAMINATION OF AIR		
	• *	
		•
		•
. *·		
K. NOTICEABLE GOORS		•
		•
•		
,		
·		
L. CONTAMINATION OF SOIL		
en e	•	The second second second
	•	
\sim	×.	A
\$. Q		
M. PROPERTY DAMAGE		
•		J.
. •		•
		•
	•	
	, * · · · · · · · · · · · · · · · · · ·	

N. FIRE OR EXPLOSION	VIII. HAZARD DESCRIPTION (continued)	
County of the way make a property		
·		
		•
	•	
O. SPILLS/LEAKING CONTAINERS/RU	HOFF/STANDING LIQUID	
**		
		-tany -
•		•
		·
·		
P. SEWER, STORM DRAIN PROBLEMS		
	•	· · · · · · · · · · · · · · · · · · ·
	-	•
·		•
		•
•	• •	
Q. EROSION PROBLEMS		
•		
	•	
·		
R. INADEQUATE SECURITY		
م المراجع المحمد المراجع	•	
	•	Automorphism of the control of the c
	·	
	A	A
		.
		دور
STEAM SETTAGENOSHI		the first of the second
•	<i>}</i> .	
•		
·		• .
		Č .

		VIII. HAZARD DES	CRIPTION (continued)			
T. MIDNIGHT DUMPING						
	-	_				•
	•		•		•	
·		-				
*	~ <u> </u>		•			
U. OTHER (specity):		"	····			
		•				
	·					*
·						
•				٠	.*	
			•			
	•					
					·	
_						
,				•	•	
·			•			
•		•		•	•	
			·		.	
	1X. F	OPULATION DIREC	TLY AFFECTED BY S	ITE		
ALLOCATION OF POPULATION		APPROX. NO.	C. APPROX. NO. OF PEC	PLE	D. APPROX. NO. OF BUILDINGS	E. DISTANCE TO SITE
	OF PE	OPLE AFFECTED	AFFECTED WITHIN UNIT AREA		AFFECTED	(apecify unita)
t, IN RESIDENTIAL AREAS		£ 500	5 500		3 450	<1 mile
·		5,500	5,500		1,450	× 1 101116
AND SERVICE THE SERVICE TO SERVIC	•	1,100	1,100		35	<1 mile
IN PUBLICLY		. ,				
4. TRAVELLES AREAS	1	70,000	170,000		. 0	<1 mile
PUBLIC USE AREAS (perks, schools, etc.)	}	2 444				
"(parks, schools, see.)	L	2,500	2,500		3	/≪l mile
A. DEPTH TO GROUNDWATER APPEL	ly unit)	S. DIRECTION OF NE	HYDROLOGICAL DA	12. G	ROUND ATER USE IN	VICINITY
270 feet 'C'; 360 feet	: "'E'*	Journeaster	1 3 5 5 5		None	بو
D. POTENTIAL YIELD OF AQUIFER		E. DISTANCE TO DRI (specify unit of mos	NKING WATER SUPPLY	F. 01	Hest	G WATER SUPPLY
3,000 gpm* .	2		. 0 911162	<u> </u>	nest	
G. TYPE OF DRINKING WATER SUP		MITY (massife must-	City of House	nn .	Tovas	
1. NON-COMMUNITY (Y)	> 18 C	HITY (opecity mon): MNECTIONS	City of Houst	UI: •	I CAUS	
A SURFACE WATER	4 WELL					
					سيب ميزج سيدسد سيدس	- On Page 9

*See Attachment A

H. LIST ALL OF	HAKING WATER WEL	X. WATER AND HYDROLOGICAL D LS WITHIN A 1/4 MILE BADIUS OF SITE	ATA (continued)		
1. WELL	E. OERTH (apacity unit)	3. LÓCATIC (proximíry to populatio	N V buildings)	HON-COM- MUNITY (mail 'X')	COMMUN-
None			·		
	 				
					<u> </u>
			·]

RECEIVING W					<u> </u>
, NAME	1	() 2. SKWERS () 3. ST	MEAMS/RIVEMS	e .	
louston Sh	ip Channel	·			
	i	A. LAKES/RESERVOIRS S. 01	HER(specify):		
		contact recreation			÷
··-·· : : : : : : : : : : : : : : : : :		•			
				· · · · · · · · · · · · · · · · · · ·	
OCATION OF S	ITE IS IN:	XI. SOIL AND VEGITATION	DATA		····
A. KNOWN	FAULT ZONE	. KARST ZONE . C.	100 YEAR FLOOD PLAIN	D. WETLAND	;
		Complete Manager Comp	RECHARGE ZONE OR SOLE SO	UOCE ACUIEFR	
E. A REGU	LATED FLOODWAY	XII. TYPE OF GEOLOGICAL MATER		OUCE NOTIFE	
ark 'X' to indi	cate the type(s) of	geological material observed and specify		nt parts.	
A. CVERBU	ADEN X	8. BEDROCK (specify below)	C. OTHER	pocity bolow)	
1. SAND					
				·	
2. CLAY	X +hic	Lake Charles-Urban Land Control of the Land	omplex Palsus buckled stree	te .	
3. SRAVEL		sidewalks, cracked walls		**·	·
		XIII. SOIL PERMEABIL			
		AUL. SOIL PERMENDIL			Δ
A. UNKHÓW		B. VERY HIGH (100,000 to 1000 cm/	ec.) C. HIGH (1000 to 10	- cm/sec.) 10	' to bel
. RECHARGE A	TE (10 to .1 cm/sec.)	E. LOW (,1 10 .001 cm/sec.)	RZ P. VERY LOW (.OOI	10 .00001 cm/#	10-2 CII
1. YES		MMENTS:			
DISCHARGE A			· · · · · · · · · · · · · · · · · · ·		
C I. YES	₩ 2. NO 3. CC	PAGENTS:	<u>A</u>		
, SLUFE I. ESTIMATE N	OF SLOPE 2. SF		ON PLORE STE.		
Flat (<15) Tov	ards N/NW if any slope at a	M. 👸 🙀		
redominan	t strata is o	of the Pleistocene Age Houst	on Group. This con	sists of c	omplexly
structured	deltaic and	marine sands and clays. Th	e primary aquifers.	Chicot and	d Evan-
geline, ár	e underlain b	by the Burkeville confining	layer (mostly clay)	, and the D	Upper
and Lower	units of the	deeper Jasper aquifer. The	Jasper does not sup	iply Houst	on with
water. Th	e Evangeline	aquifer, used most often in	the Houston area.	(Sec Attaci	hment A)

*See Attachment A

			D. DATE	E. EXPIRATION		COMPLIA (X)	
A. PROMIT TYPE MA.RCRA, SIMM, NPDES, MIG.)	AGENCY	C. PERMIT HUMBER	ISSUE ? {#101, #37, £ 371, }	OATE (Y#3	2. NO	1.UN-
Commercial	FDWR	39040	8-31-81	8-31-91		X	
Wastewater dischar	City of Be Houston		2-12-81				
	-	***************************************					-

None YES (wammerine in this space)

Currently under enforcement for:

- Receipt of unauthorized waste (1, 1, 1, trichloroethane)
 Failure to maintain a mechanism for financial assurance

NOTE: Based on the information in Sections III through XV, fill out the Tentative Disposition (Section II) information on the first page of this form.

EPA Fam T2070-3 (10-79)

PAGE 10 OF 10

ATTACHMENT A

POTENTIAL HAZARDOUS WASTE SITE SITE INSPECTION REPORT SUPPLEMENT SHEET

Instruction - This sheet is provided to give additional information in explanation of a question on the form T2070-3.

Corresponding number on form

Additional Remark and/or Explanation

X-A

These 1975 measurements of water levels in the two shallowest janor Houston Area aquifers are intended to indicate minimum water levels in respective walls in 1984. Water levels declined 45 feet in Chicot aquifer completed wells from 1965 to 1975, and, in the deeper Evangeline aquifer during that same period, they dropped 65 feet under the scrutinized site. A 270 ft depth measure for the Chicot (C) and for the Evangeline (E) are indicated for 1975 in Section A. Several wells, 2 to 3 miles distant from the site, tap the Upper Chicot aquifer where well bore water levels are as shallow as 12 feet. (Refer to TDWR R241, 1980)

X-0

Combining pumpage yield from both the lower Chicot and the Evangeline aquifers within a single wellbore has pulled yields as high as 3,000 gallons per minute (indicated figure). Actual pumping yields in the Chicot aquifer itself range from about 150 to 1,050 gpm and from 200 to 2,400 gpm in the Evangeline aquifer. (Refer to TDWR R203, 1976)

ŘIII-J

completes with the secondary Chicot aquifer when saline water exists within the Evangeline. Thicknesses of these hydrologic units in the site area range from approximately 160 feet in the Upper Chicot and 460 feet in the Lower Chicot to about 1,800 feet in the Evangeline. The Burkeville maintains a 250 feet effective thickness. Strata dip to the Southeast, but vary southerly with type of depositional deposit. (Refer to TDWR R241, 1980. Figure 4).

	{5u	TIES SITE INSPECTION R Professional Reports	EPORT		INSTRUCTION Necessary.	,
71 483	ARCA NAS CONTINUOUS IMPE (内) NO					
W + E #	O NO COMPLETENTS		421		·	
	compretery e	enclosed by concrete of the contract and then	11Ke	end me forebre : fema. o	and the second of the S	
C) 141	□ •••					•
•		•	. •			
	·			•		
		•			•	
None	TYPE AND HUMBER OF BARR	ELS/CONTAINERS				
	LASTIC STORAGE CONTAINE	AS USED				
□ 783			<u></u>			:
	ertical tanks approx	imately 250,000 g 1.	total			
HOTE LABE	LING ON CONTAINERS			<u> </u>		
N/A	•					
W/ M						
	-			•		:
		•			. • •	
	• '			•		
	•					
VIDENCE O	IF LEARAGE CORRESION OR	BULGING OF BARNELS/CONTA	INERUSTORAGE TAN	AS (16"Yes", docum	nt pridence. Drze	ur ë
	F LEARAGE CORRESION OR I	BULGING OF EARNELS/CONTA GRAPHS)	INERS STORAGE TAN	RS (1311): 4011, docum	int e ridence, Drei	urbe
	***.	BULGING OF EARNELS/CONTA GRAPHS)	INERSISTORAGE TAN	AS film Y do ", docum	ent goldenca, Dos a	gr ā a
	***.	BULGING OF EXPREUS/CONTA CRAPHS)	INERS STORAGE TAN	AS filt"Pee", docum	ent Gridence . Bosc	Le ğ #
	***.	BULGING OF ELRHELS/CONTA GRAPHS)	INERS STORAGE TAN	AS fil ^{er} Y ee", d ocum	ini e ridence . "Doss	urike
	***.	BULGING OF EARHELS/CONTA GRAPHS)	INERS STORAGE TAN	AS fil"Y ae", docum	ent gridence s "Dose	ur a e
	***.	BULGING OF EARHELS/CONTA CRAPHS)	INERS STORAGE TAN	AS filt Paors docum	ent Gridence. "Bose	ura.
	***.	BULGING OF EXAMELS/CONTA	INERS STORAGE TAN	AS fight been decum	ent oridon co. Desd	ura-
	***.	BULGING OF EARHELS/CONTA	INERS STORAGE TAN	AS filt Y ac '', docum	int goldenes . Dose	
	MO:	BULGING OF EARHELS/CONTA	INERS STORAGE TAN	AS (it "Yee", docum	ent ovidences, Bose	urbe
DIRECT VEN	TING OF STORAGE TANKS	BULGING OF ELAHELS/CONTA	INERS STORAGE TAN	AS filt Page docum	ent doidence. Dosc	ura.
DIRECT VEN	TING OF STORAGE TANKS NO IS NOLDING INCOMPATIBLE S	BULGING OF EARHELS/CONTA				
DIRECT VEN	TING OF STORAGE TANKS	UESTANCES (II "Yes", decumen				
DIRECT VEN	TING OF STORAGE TANKS MO IS NOLDING INCOMPATIBLE SI PROTOGRAPHS NO	UESTANCES (II "Yes", decueen				
DIRECT VEN	TING OF STORAGE TANKS THO IS NOLDING INCOMPATIBLE STORAGE PHOTOGRAPHS.	UESTANCES (II "Yes", decumen				
DIRECT VEN	TING OF STORAGE TANKS MO IS NOLDING INCOMPATIBLE SI PROTOGRAPHS NO	UESTANCES (II "Yes", decumen				
DIRECT VEN THES CONTAINER THES TES	TING OF STORAGE TANKS HO IS NOLDING INCOMPATIBLE SI PHOTOGRAPHSJ NO BLE SUBSTANCES STORED IN	UESTANCES (II "Yes", decumen	or evidence, "Describe b	ocotion and identity	ol Suzardovo	
DIRECT VEN THES THES THES THES THES	TING OF STORAGE TANKS NO IS NOLDING INCOMPATIBLE SI PHOTOGRAPHS PLE SUBSTANCES STORED IN PORT, Toke PMOTOGRAPHS	UBSTANCES (II "Fee", decumen	or evidence, "Describe b	ocotion and identity	ol Suzardovo	
DIRECT VEN TYES CONTAINER THES THES THES	TING OF STORAGE TANKS HO IS NOLDING INCOMPATIBLE SI PHOTOGRAPHSJ NO BLE SUBSTANCES STORED IN	UBSTANCES (II "Fee", decumen	or evidence, "Describe b	ocotion and identity	ol Suzardovo	
DIRECT VEN TYES CONTAINER THES THES THES	TING OF STORAGE TANKS NO IS NOLDING INCOMPATIBLE SI PHOTOGRAPHS PLE SUBSTANCES STORED IN PORT, Toke PMOTOGRAPHS	UBSTANCES (II "Fee", decumen	or evidence, "Describe b	ocotion and identity	ol Suzardovo	
DIRECT VEN TYES CONTAINER THES THES THES	TING OF STORAGE TANKS NO IS NOLDING INCOMPATIBLE SI PHOTOGRAPHS PLE SUBSTANCES STORED IN PORT, Toke PMOTOGRAPHS	UBSTANCES (II "Fee", decumen	or evidence, "Describe b	ocotion and identity	ol Suzardovo	
DIRECT VEN TES CONTAINER BASIS. Take TES INCOMPATE ASSOCIATE VES	TING OF STORAGE TANKS NO IS NOLDING INCOMPATIBLE SI PHOTOGRAPHS PLE SUBSTANCES STORED IN PORT, Toke PMOTOGRAPHS	UESTANCES (II "Yes", documen	or evidence, "Describe b	ocation and identity o	ol Suzardovo	

RCRA 3012 SITE INSPECTION COMMENTS FORCE, INC. HOUSTON, TEXAS TX03115

Tom Stang and Philip Liang from Engineering-Science, along with Susan Ripley from the TDWR Region 7, inspected Force, Inc. on February 16, 1984. The Time of the inspection was from 8:30 in the morning until 11:30. Present for Force, Inc. were Don Forse, President, James Greenlee, the Environmental Compliance Officer, and Homer Shealy, Treasurer of Force, Inc. Force, Inc. is an oil reclaim outfit. Force receives waste oil and waste oil emulsions from various industries and processes them through their plant on Lawndale Avenue. Force also transports the waste oil in their own vacuum trucks. The company is not a hazardous waste generator, transporter or disposer. recycle/reclaim operation strictly in the business of reclaiming oil from waste oils and waste oil emulsions. The site is permitted through the State of Texas (TDWR) as a commercial recycler. The waste oils which they treat are considered to be Class I waste; however, they are not considered to be hazardous waste. The site is not permitted to receive any hazardous waste and as such, Force, Inc. is not permitted as a hazardous waste management facility. The Force, Inc. operations consist of receiving waste oil in vacuum trucks, unloading the trucks into a belowground sump, pumping the waste oil into a receiving tank, allowing for phase separation, treating the wastewater through dissolved air flotation (DAF) aided by a cationic polymer, and disposing of the water through the municipal sewer. The oil which is separated from the wastewater is pumped to one of two holding tanks from where it is pumped to their vacuum truck and sold to various customers. The City of Houston frequently monitors the water which has been treated. Force has indicated that they have never had a violation or any problems with the water that they discharge to the municipal sewer. At the time of the inspection, the site appeared clean and free from any oil spills. There was no evidence of unauthorized waste receipt and for the most part, Force, Inc. looked to be fairly well run.

Force, Inc. is currently under enforcement action by the State of Texas (TDWR). The enforcement action is due to the unauthorized receipt of oil

containing 1,1,1 trichloroethane back in 1983. The solvent was received in a shipment of waste oil which the company allegedly intended to process regardless of this unauthorized contaminant. The contaminated oil was eventually returned to the customer. Even though there is continued enforcement action, there does not appear to be any deleterious aftereffects of receiving the unauthorized shipment. Current operations appear to be in compliance with their permit. There is no indication of unauthorized receipt of waste. The facility looked to be well maintained and operated. It is the recommendation of this inspection team that Force, Inc. not be considered for further action under the RCRA 3012 program.